



Your Inspection Report

184 Wright Avenue
Toronto, ON M6R 1L2

PREPARED FOR:

KIM KEHOE
LISTING AGENT

INSPECTION DATE:

Monday, June 22, 2026

PREPARED BY:

Scott Aitken

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

4164074663
scottaitken@live.ca

July 20, 2026

Dear Kim Kehoe and Listing Agent,

RE: Report No. 4568, v.2
184 Wright Avenue
Toronto, ON
M6R 1L2

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken
on behalf of
Aitken Home Inspections

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2
4164074663

scottaitken@live.ca

AGREEMENT

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

PARTIES TO THE AGREEMENT

Company

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

Client

Kim Kehoe

Client

Listing Agent

This is an agreement between Kim Kehoe, Listing Agent and Aitken Home Inspections.

THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.
PLEASE READ CAREFULLY BEFORE SIGNING.

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

AGREEMENT

184 Wright Avenue, Toronto, ON June 22, 2026

Report No. 4568, v.2

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

AGREEMENT

184 Wright Avenue, Toronto, ON June 22, 2026

Report No. 4568, v.2

8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

I, Kim Kehoe (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

I, Listing Agent (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

SUMMARY

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Home in good condition.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

ROOFING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description


The home is considered to face: • South

Sloped roofing material:

- Composition shingles



1.



2.

Flat roofing material:

- [Modified bitumen membrane](#)



3.



4.

ROOFING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Probability of leakage: • Medium

Approximate age:

• 5 years

At sloped roof.

• 12 years

At flat roof.

Limitations

Inspection limited/prevented by:

• Deck, could not inspect roof membrane below.



5.

Inspection performed: • By walking on roof

Age determined by: • Reported by seller

Recommendations

FLAT ROOFING \ Modified bitumen

1. Condition: • [Openings at seams or flashings](#)

Reseal perimeter of upper flat roof.

Implication(s): Chance of water damage to structure, finishes and contents

Task: Repair

Time: Regular maintenance

Cost: Minor

ROOFING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



6.

EXTERIOR

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Gutter & downspout material: • [Aluminum](#)

Downspout discharge: • [Below grade](#) • [Above grade](#)

Lot slope: • [Flat](#)

Soffit (underside of eaves) and fascia (front edge of eaves): • [Wood](#)

Wall surfaces and trim: • [Metal siding](#) • [Brick](#)

Retaining wall: • [Concrete](#)

Walkway: • Interlocking brick

Deck: • Concrete

Porch: • Wood • Brick

Balcony: • Pressure-treated wood

Patio: • Interlocking brick

Garage: • Detached • Wood Frame

Limitations

Inspection limited/prevented by: • Car/storage in garage • Vines/shrubs/trees against wall

Recommendations

ROOF DRAINAGE \ Downspouts

2. Condition: • [Discharge below grade](#)

Disconnect downspout and route well away from foundation.

Implication(s): Chance of water damage to structure, finishes and contents

Location: East Exterior

Task: Improve

Time: Unpredictable

Cost: Minor

EXTERIOR

184 Wright Avenue, Toronto, ON June 22, 2026

Report No. 4568, v.2

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING


COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



7.

EXTERIOR

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

WALLS \ Trim

3. Condition: • Typical paint and caulking maintenance needed.

Seller to have wood prep and paint completed at exterior.

Location: Throughout Exterior



8.

WALLS \ Masonry (brick, stone) and concrete

4. Condition: • [Parging damaged or missing](#)

Implication(s): Chance of damage to structure | Shortened life expectancy of material

Location: West Exterior

Task: Repair

Time: Regular maintenance

Cost: Minor

EXTERIOR

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



9.

GARAGE \ Floor

5. Condition: • Garage floor is below lane level, monitor for water entry and need to install drainage.

Location: Garage

Task: Monitor


Cost: Depends on work needed

EXTERIOR

184 Wright Avenue, Toronto, ON June 22, 2026

Report No. 4568, v.2

SUMMARY	ROOFING	EXTERIOR	STRUCTURE	ELECTRICAL	HEATING	COOLING	INSULATION	PLUMBING	INTERIOR
REFERENCE									



10.

Description

Configuration: • [Basement](#)

Foundation material:

- [Stone](#)
 - Not visible
- At addition

Floor construction: • [Joists](#) • Subfloor - plank

Exterior wall construction:

- [Wood frame](#)
- At addition.
- [Masonry](#)

Roof and ceiling framing: • [Rafters/roof joists](#) • Not visible

Limitations

Attic/roof space:

- No access
- Typical with this roofline.

Percent of foundation not visible: • 95 %

Recommendations

RECOMMENDATIONS \ Overview

- 6. Condition:** • No structure recommendations are offered as a result of this inspection.
- 7. Condition:** • All visible structural members in good condition.

Description

Service entrance cable and location: • [Overhead copper](#)

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box rating: • [100 Amps](#)

Main disconnect/service box type and location: • [Breakers - basement](#)

System grounding material and type: • [Copper - water pipe](#)

Distribution panel type and location:

• [Breakers - basement](#)



11.

Distribution panel rating: • [100 Amps](#)

Distribution wire (conductor) material and type: • [Copper - non-metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - typical](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • [GFCIs present](#) • [AFCI - panel](#)

Smoke alarms (detectors): • [Present](#)

Limitations

Not included as part of a building inspection: • Concealed Wiring

Recommendations

DISTRIBUTION SYSTEM \ Wiring (wires) - installation

8. Condition: • Cover exposed wiring with conduit.

Location: Kitchen

Task: Protect

Time: Immediate

Cost: Minor



12.

HEATING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Heating system type: • Combi-boiler. High efficiency boiler and tankless water heater combined.

Fuel/energy source: • [Gas](#)

Heat distribution: • [Radiators](#)

Approximate capacity: • [90,000 BTU/hr](#)

Efficiency: • [High-efficiency](#)

Combustion air source: • Outside

Approximate age: • [6 years](#)

Main fuel shut off at: • Meter

Failure probability: • [Low](#)

Auxiliary heat:

- [Electric baseboard heater](#)
- Radiant floor heating (electric)



13.

- Heat pump.

Chimney/vent:

- [Abandoned](#)

HEATING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



14. Not in use

- High temperature plastic
- Sidewall venting

Condensate system: • Electric pump

Limitations

Warm weather: • Prevents testing heating effectiveness

Heat loss calculations: • Not done as part of a building inspection

Recommendations

RECOMMENDATIONS \ Overview

9. Condition: • No heating recommendations are offered as a result of this inspection.

COOLING & HEAT PUMP

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Air conditioning type:

- [Ductless \(Mini split\) system](#)

x2

Cooling capacity:

- [24,000 BTU/hr](#)

x2

Compressor approximate age: • 6 years

Failure probability: • [Low](#)

Limitations

Heat gain calculations: • Not done as part of a building inspection

Recommendations

RECOMMENDATIONS \ Overview

10. Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection. Systems in good working order.

INSULATION AND VENTILATION

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Attic/roof insulation material: • Not determined

Attic/roof insulation amount/value: • Not determined

Attic/roof ventilation: • [Roof vent](#)

Wall insulation material: • [Glass fiber](#)

Wall insulation amount/value: • Spot checked only • 0-12

Wall air/vapor barrier: • Plastic

Foundation wall insulation material: • [Glass fiber](#) • Spray foam.

Foundation wall insulation amount/value: • 0 - R20

Limitations

Inspection limited/prevented by lack of access to: • Roof space

Recommendations

RECOMMENDATIONS \ Overview

11. Condition: • Increased insulation is an improvement and not an essential repair.

Description

Water supply source (based on observed evidence): • Public

Service piping into building:

• [Copper](#)


3/4 inch

Supply piping in building: • [Copper](#) • PEX (cross-linked Polyethylene)

Main water shut off valve at the:

• South

• Basement



15.

Water flow and pressure: • Good

Water heater type: • Combi boiler

Water heater fuel/energy source: • [Gas](#)

Water heater approximate age: • 6 years

Water heater failure probability: • [Low](#)

Waste and vent piping in building: • [ABS plastic](#)

Pumps:

• [Sump pump](#)



16.

Floor drain location: • Near laundry area

Backwater valve:

- Not visible
- Seller states backwater valve is present at south basement under carpet.

Limitations

Items excluded from a building inspection: • Concealed plumbing

Recommendations

WASTE PLUMBING \ Drain piping - performance

- 12. Condition:** • Recommend video inspection of main drains due to age and proximity of very large tree.
- Location:** South Exterior
- Task:** Further evaluation

WASTE PLUMBING \ Venting system

- 13. Condition:** • Noisy tub drain and slow toilet flush are likely due to lack of venting. Correction would likely be invasive.
- Implication(s):** Slow drains can clog easily.
- Location:** Basement Bathroom
- Task:** Further evaluation

FIXTURES AND FAUCETS \ Shower stall

- 14. Condition:** • [Entrance problems](#)

PLUMBING

Report No. 4568, v.2

184 Wright Avenue, Toronto, ON June 22, 2026

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Replace missing handle at second floor, add door stop to prevent contact of glass with shower head.

Implication(s): Difficult access

Location: Second Floor Third Floor

Task: Improve

Time: Unpredictable

Cost: Minor



17.



18.

Description

Major floor finishes: • [Carpet](#) • Ceramic/porcelain • Engineered wood

Major wall finishes: • [Plaster/drywall](#)

Major ceiling finishes: • [Plaster/drywall](#)

Windows: • [Fixed](#) • [Single/double hung](#) • [Sliders](#) • [Casement](#) • [Awning](#)

Glazing: • [Double](#)

Exterior doors - type/material: • Hinged • [Wood](#)

Evidence of basement leakage: • None

Limitations

Inspection limited/prevented by: • Storage/furnishings

Not included as part of a building inspection: • Appliances

Percent of foundation not visible: • 95 %

Recommendations

RECOMMENDATIONS \ Overview

15. Condition: • Typical minor cosmetic flaws present.

END OF REPORT

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS