



441 Butler St. Springdale, PA 15144

412-461-8273 Fax: 412-461-0814

www.hometeam.com/southpittsburgh

E-mail: southpittsburgh@hometeam.com

HomeTeam[®] INSPECTION SERVICE

**1281 Washington Rd
RE: Pittsburgh, PA 15228
Inspection #: 527-062026-6954**

Dear Michael Rathbun,

On 6/30/2026 HomeTeam Inspection Service made a visual inspection of the property referenced above. Enclosed please find a written, narrative report of our findings in accordance with the terms of our Home Inspection Agreement. Although maintenance items may have been addressed verbally at the time of the inspection, they may not be included in the enclosed report.

I trust the enclosed information is helpful and I hope you enjoy every aspect of your new home. If I can be of any assistance, please feel free to call me at the above telephone number.

Sincerely,

**HomeTeam Inspection Service
Mike Pucci**

PA Radon Firm Certification #2915





HomeTeam[®]

INSPECTION SERVICE

HOME INSPECTION REPORT



Home. Safe. Home.



HomeTeam[®]
INSPECTION SERVICE



CONVENIENT | EFFICIENT &
BOOKINGS | INSPECTIONS
FAST REPORTS

WHAT IS A HOME INSPECTION?

The purpose of a home inspection is to visually examine the readily accessible systems and components of the home. The inspectors are not required to move personal property, materials or any other objects that may impede access or limit visibility. Items that are unsafe or not functioning, in the opinion of the inspector, will be described in accordance with the standards of practice by which inspectors abide.

WHAT DOES THIS REPORT MEAN TO YOU?

This inspection report is not intended as a guarantee, warranty or an insurance policy. Because your home is one of the largest investments you will ever make, use the information provided in this report and discuss the findings with your real estate agent and family to understand the current condition of the home.

OUR INSPECTIONS EXCEED THE HIGHEST INDUSTRY STANDARDS.

Because we use a team of inspectors, each an expert in his or her field, our inspections are performed with greater efficiency and more expertise and therefore exceed the highest industry standards. We are pleased to provide this detailed report as a service to you, our client.

WE BELIEVE IN YOUR DREAM OF HOME OWNERSHIP.

We want to help you get into your dream home. Therefore, we take great pride in assisting you with this decision making process. This is certainly a major achievement in your life. We are happy to be part of this important occasion and we appreciate the opportunity to help you realize your dream.

WE EXCEED YOUR EXPECTATIONS.

Buying your new home is a major decision. Much hinges on the current condition of the home you have chosen. That is why we have developed the HomeTeam Inspection Report. Backed by HomeTeam's experience with hundreds of thousands of home inspections over the years, the report in your hand has been uniquely designed to meet and exceed the expectations of today's homebuyers. We are proud to deliver this high-quality document for your peace of mind. If you have any questions while reviewing this report, please contact us immediately.

Thank you for allowing us the opportunity to serve you.



FAST



TRUSTED



ACCURATE

PREFACE:

This report is intended for the sole, confidential, and exclusive use and benefit of the Client(s) under a written HomeTeam Inspection Agreement. This report is not intended for the benefit of, and may not be relied upon by, any other party. The disclosure or distribution of this report to the current owner(s) of the property inspected or to any real estate agent will not make those persons intended beneficiaries of this report. HomeTeam Inspection Service has no liability to any party (other than the HomeTeam client named above, for whom this report was expressly prepared) for any loss, damage or expense (including, without limitation, attorney fees) arising from any claim relating to this report.

A home inspection is intended to assist in evaluation of the overall condition of the dwelling. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection. We will not render an opinion as to the condition of any systems or components of the structure that are concealed by walls, floors, drywall, paneling, suspended ceiling tiles, insulation, carpeting, furniture or any other items stored in or on the property at the time of the inspection.

The results of this home inspection are not intended to make any representation regarding the presence or absence of latent or concealed defects that are not reasonably ascertainable in a competently performed home inspection. No warranty or guaranty is expressed or implied.

If the person conducting your home inspection is not a licensed structural engineer or other professional whose license authorizes the rendering of an opinion as to the structural integrity of a building or its other component parts, you may be advised to seek professional opinion as to any defects or concerns mentioned in the report. If the age, condition or operation of any system, structure or component of the property is of a concern to you, it is recommended that a specialist in the respective field be consulted for a more technically exhaustive evaluation.

This home inspection report is not to be construed as an appraisal and may not be used as such for any purpose.

This inspection report includes a description of any material defects (*) noted during the inspection, along with any recommendation that certain experts be retained to determine the extent of the defects and any corrective action that should be taken. Any material defect that poses an unreasonable risk to people on the property will be conspicuously defined as such. Any recommendations made to consult with other specialists for further evaluation as a result of our findings should be complete prior to the conclusion of the inspection contingency period. The Client warrants they will read the entire Inspection Report when received and shall promptly contact HomeTeam regarding any questions or concerns the Client may have regarding the inspection or the Inspection Report.

The majority of home inspections are performed on pre-existing structures. The age of these structures vary from just a few years to over 99 years old. Building techniques have changed dramatically over the years. These changes are what bring character to the neighborhoods of Western Pennsylvania, and affect a buyer's decision to purchase one home over another. Therefore, the age and method of construction will affect the individual character of a home.

We will not determine the cause of any condition or deficiency, determine future conditions that may occur including the failure of systems and components or consequential damage or components or determine the operating costs of systems or components.

It is not uncommon to observe cracks or for cracks to occur in concrete slabs or exterior and interior walls. Cracks may be caused by curing of building materials, temperature variations and soil movement such as: settlement, uneven moisture content in the soil, shock waves, vibrations, etc. While cracks may not necessarily affect the structural integrity of a building, cracks should be monitored so that appropriate maintenance can be performed if movement continues at an abnormal rate. Proper foundation maintenance is key to the prevention of initial cracks or cracks enlarging. This includes, but not limited to proper watering, foundation drainage and removal of vegetation growth near the foundation.

* Material Defect: A problem with a residential real property or any portion of it that would have a significant adverse impact on the value of the property or that involves an unreasonable risk to the people on the property. The fact that a structural element, system or subsystem is near, at or beyond the end of the normal useful life of such a structural element, system or subsystem is not by itself a material defect.

SUMMARY: The purpose of this summary is to provide a "quick view" of the results of the home inspection. Please be sure to read the full body of the inspection report, as it contains much more detail about your new home. Any recommendations for additional evaluation must be performed prior to the conclusion of the inspection contingency period. You should ask the seller to provide receipts or other suitable documentation as evidence that items requested as part of the reply to home inspection were complete by qualified individuals.

The following notable items were observed during the inspection performed at 1281 Washington Rd, Pittsburgh, PA 15228:

PLEASE NOTE each summary bullet point is a link. Simple click on the bullet point to drop down into that section of the report.

Safety Concerns

- There were several trip hazards found on the walkways around the house.
- There was no handrail on the stairs leading from the garage. This can be a safety concern.
- 3 window (s) would not lock.
- There is a missing handrail on the stairs leading to the 3rd floor.
- The handrail on the stairs leading to the basement is loose or otherwise insecure.

General Description

- Missing mortar was noted on the brickwork on several areas of the home.
- The front left retaining wall is leaning inward.
- One or more cracks were noted on the brick veneer of the home.
- The right retaining wall is cracked and leaning inward.
- Missing mortar was noted on the brickwork on the front retaining wall of the home.

Roof Structure

- Missing fascia was noted on the front.
- The rain hat on top of the chimney is missing.

Garage

- There were signs of moisture on the right garage wall.

Foundation

- The radon mitigation system installed in the home did not appear to be working properly at the time of the inspection.

Floor Structure

- Evidence of termite activity was noted on the basement floor joists.
- The floor joists are water marked below the kitchen basement floor structure.

Basement

- There were signs of moisture on the left basement wall.

Windows, Doors, Walls and Ceilings:

- One or more defective tilt latches were noted on the windows.

First Level

- Water marks with some surface damage was noted on the ceiling at a skylight.

Attic Structure

- The attic ventilation was questionable. No vents could be viewed

Heating & Air Conditioning

- The insulation on the exterior air conditioning line set is damaged.
- There was evidence the boiler control was leaking.
- The boiler was not functional at the time of the inspection. The unit was in shut down mode due to high outside temperatures. Consult with a qualified heating contractor to confirm operation if desired.
- Water was noted in the attic air handler condensate pan. The condition appears to be the result of high temperatures and humidity in the attic. The system was operating as designed. If desired, the attic space will have to be modified to better control the air temperature. Repairs should be made by a qualified contractor if desired.

GENERAL DESCRIPTION

Throughout this report, the terms "right" and "left" are used to describe the home as viewed from the street. A system or component has a material defect if it has a significant impact on the value or safety of the property. The HomeTeam inspects for evidence of structural failure and safety concerns only. The cosmetic condition of the paint, wall covering, carpeting, window coverings, etc., are not addressed. All conditions are reported as they existed at the time of the inspection. Routine maintenance and safety items are not within the scope of this inspection unless they otherwise constitute material visually observable defects. Although some maintenance and/or safety items may be disclosed, this report does not include all maintenance or safety items, and should not be relied upon for such items.

The inspected property consisted of a two story wood-framed structure with brick veneer that was occupied at the time of the inspection. There were no material defects on the visible portions of the siding.

MAINTENANCE NOTE: EXTERIOR SEALANT:

The exterior caulking around the windows and doors is cracked or missing on all sides of the home. The caulking should be replaced to ensure the exterior of the home remains weather and water tight.



NOTE: MISSING MORTAR:

Missing mortar was noted on the brickwork on several areas of the home. There were no loose bricks noted. Small amounts of missing mortar are usually inconsequential. Extensive amounts of missing mortar can permit water intrusion. Consult with a qualified masonry contractor for repair estimates.



NOTE: MASONARY/MORTAR CRACKS:

One or more cracks were noted on the brick veneer of the home. The cracks were located on the back. The cracks appear to have been caused by expansion and contraction, are common and do not usually have any structural significance. No structural concern on the brickwork was noted at the time of the inspection. All cracks should be monitored for significant changes in characteristics. Corrective action has been taken. No additional action appeared to be necessary at the time of the inspection.



The approximate temperature at the time of the inspection was 85 to 90 degrees Fahrenheit, and the weather was sunny and clear. The owner was present at the time of the inspection. All of the utilities were on at the time of the inspection.

LOT AND GRADE

The home was situated on a moderately sloped lot. The general grade around the home appeared to be questionable on the back to direct rain water away from the foundation. The age of the home, as reported by the MLS sheet was said to be ninety to one hundred years old. The inspection does not include any geological surveys, soil compaction surveys, ground testing, or evaluation of the effects of, or potential for earth movement such as earthquakes, landslides, sinking, rising or shifting for any reason. Information on local soil conditions and issues should be obtained from local officials and/or a qualified specialist. Additionally, the inspection does not include evaluation of elements such as underground drainage systems, site lighting, irrigation systems, barbecues, sheds, detached structures, fencing, privacy walls, pools, spas and other recreational items.

WALKWAY AND PORCHES

There was a concrete walkway leading to a concrete entry way in the front of the home. Surface defects in walkways develop and progress with age and are considered normal as long as they do not create a safety hazard. There were no material defects observed in the walkway or the front entry way.

SAFETY NOTE: TRIP HAZARDS:

There were several trip hazards found on the walkways around the house. The hazards can be repaired using a suitable or similar surfacing material to "feather" the out-of-level condition to make a smooth transition.



There was a brick and Block located in the back of the home. There were no material defects observed to the patio.



RETAINING WALL

There were two retaining walls constructed of brick and block. The walls were in serviceable condition. There were no material defects observed in the wall. We do not inspect or comment on retaining walls that are detached from the main structure of the home unless the walls function has an impact on the structure.

NOTE: RETAINING WALL:

The front left retaining wall is leaning inward. There were significant vertical earth pressure type cracks observed in the wall. This condition is most often associated with soil and /or water pressure. The displacement occurs incrementally as the wall yields to horizontal earth pressure. The wall was stable at the time of the inspection. Repairs to the wall may be required. Consult with a qualified contractor for repair estimates



NOTE: RETAINING WALL:

The right retaining wall is cracked and leaning inward. There were significant vertical earth pressure type cracks observed in the wall. This condition is most often associated with soil and /or water pressure. The displacement occurs incrementally as the wall yields to horizontal earth pressure. The wall was stable at the time of the inspection. Repairs to the wall may be required. Consult with a qualified contractor for repair estimates




NOTE: MISSING MORTAR:

Missing mortar was noted on the brickwork on the front retaining wall of the home. There were no loose bricks noted. Small amounts of missing mortar are usually inconsequential. Extensive amounts of missing mortar can permit water intrusion. Consult with a qualified masonry contractor for repair estimates.



RETAINING WALL

There was one retaining wall constructed of treated wood. The wall was in fair condition. There were no material defects observed in the wall. We do not inspect or comment on retaining walls that are detached from the main structure of the home unless the walls function has an impact on the structure.



ASPHALT DRIVEWAY

There was an asphalt driveway in the front of the home which led to the integral garage. There were many cracks and spalled areas noted on the driveway. Surface defects in driveways develop and progress with age and are considered normal as long as they do not create a safety hazard. There were no material defects observed in the driveway. Sealing the driveway with an asphalt driveway sealer will help extend the life of the driveway.



METAL ROOF

The main roof was a gable design with overlapping seam metal roofing. Observation of the roof surfaces, flashing and penetrations was performed from the ground level with the aid of binoculars. We will not walk on a metal roof due to the risk of damage and personal injury. The visible seams and joints were intact. There were no loose panels. The visible fasteners were intact. The condition of the roof panels was good. There were roof penetrations. The roof penetrations appeared to be in good condition. Roof penetrations often require maintenance. Consult with a qualified metal roofer for repair if any evidence of interior moisture along the upper interior ceiling is observed. The overall condition of the metal roof was good.

The aluminum soffit and fascia was inspected and was in good condition.

NOTE: SOFFIT & FASCIA:

Missing fascia was noted on the front. Consult with a qualified contractor for repair.



This visual roof inspection is not intended as a warranty or an estimate on the remaining life of the roof. Any roof metal, especially the flashing and valleys, must be kept well painted with a paint specially formulated for the use. All roof penetrations require maintenance and can crack, loosen or leak during or after significant weather events such as wind or rain. These areas should be monitored for changes in characteristic and repaired as required by a qualified roofer. There were no material defects detected on the exterior of the roof.


The roof drainage system consisted of aluminum gutters and downspouts which appeared to be functional at the time of the inspection. Gutters and downspouts should receive routine maintenance to prevent premature failure. There were no material defects observed on the visible portions of the gutters or downspouts.

There were two chimneys. Observation of the chimneys exterior was made from the ground with the aid of binoculars. Rain hats were installed on some of the chimneys. Rain hats are not required but can help prevent excessive water running down the chimney as well as keeping animals out. Flue chases should always have some type of rain hat. In this case rain hats are not applicable since there are no flue chases. There were no material defects observed on the exterior.



NOTE: RAIN HAT:

The rain hat on top of the chimney is missing. Repairs should be made by a qualified roofer.




Left side chimney

GARAGE WITH OPENER

The integral garage was designed for one car with access provided by one overhead-style doors. Safety cables were not required on this type of door. The Chamberlain brand electric garage door opener was tested and found to be functional. The automatic safety reverse on the garage door was tested and found to be functional. The functionality of remote transmitters, keyless entry or other opening devices is not tested during the home inspection. The fire separation walls and ceiling were inspected and did appear to be adequate. The concrete garage floor was in fair condition. There were no material defects observed in the garage or the door mechanisms.

SAFETY NOTE: MISSING HANDRAIL:

There was no handrail on the stairs leading from the garage. This can be a safety concern. Local building codes may also require the installation of a handrail.



NOTE: GARAGE MOISTURE EVIDENCE:

There were signs of moisture on the right garage wall. The area was dry at the time of the inspection. Dampness on garage walls is not always a sign of water intrusion. The dampness can be the result of warm humid air making contact with cool walls. In many cases the humid air condenses on the wall and forms a layer of moisture. It is important to assess whether moisture on the walls is the result of water intrusion or condensation. In this case, the efflorescence noted on the wall appears to be the result of moisture buildup on the exterior side of the foundation. The exterior grading in the affected area is questionable. Many water intrusion problems can be controlled by improving the drainage on the exterior of the home. It is important that all roof drainage and surface water is directed away from the foundation. The area should be monitored during periods of heavy rain to better assess the cause.



Efflorescence

INFORMATIONAL NOTE: GARAGE STORED ITEMS:

The garage was cluttered with many stored items and/or shelves at the time of inspection, therefore several areas were unable to be inspected.



FOUNDATION

The foundation was constructed of concrete block. A single inspection cannot determine whether movement of a foundation has ceased. Any cracks should be monitored regularly. There were no material defects observed on the visible portions of the foundation.

There were several minor, settlement cracks observed on the foundation. The cracks were 1/16-inch or less in width. These cracks are common and usually insignificant. All buildings experience some settlement. Settlement cracks most often occur within the first few years after construction as the soil under the structure accommodates itself to the load of the structure. However, the significance of cracks cannot always be judged by a single inspection. All cracks should be monitored for significant changes in characteristics. Consult with a company specializing in foundation repair if there is a marked change in the size or dimension of a crack.

BASEMENT

The full basement was finished, and contained the following mechanical systems: boiler and water heater. The concrete basement floor was in satisfactory condition. Minor cracks within any concrete slab are common and are most often due to shrinkage and settlement. Concrete floors are poured after the structure is built and serve no purpose with regard to structural support.

The basement stairway was inspected and there were no material defects observed with the steps, stairways or handrails.

SAFETY NOTE: LOOSE HANDRAIL:

The handrail on the stairs leading to the basement is loose or otherwise insecure. The handrail should be properly secured for safety.



Bolt loose

The finished basement area included Family, utility room, storage closet, laundry, half bath.

INFORMATIONAL NOTE: BASEMENT WALLS:

The interior walls of the basement were finished/covered; therefore, a complete inspection of the concrete block foundation was not possible. There were not material defects observed on the visible portions of the foundation.

The basement was dry at the time of the inspection. Because the basement is below grade, there exists a vulnerability to moisture penetration after heavy rains.

There was no evidence of an interior french drain system in the home. French drains are not required, but are often installed to control or prevent water intrusion. Some french drains discharge into a sump, while others do not. If a sump is present, there is a separate section of this report with details on the sump and pump, if present. Most french drain systems are concealed below the floor. As a result, it is typically not possible for us to determine the type of installation, the coverage of the system or if the system is operable. Consult with the current property owner for more information.

There were no material defects observed in the basement.

NOTE: BASEMENT MOISTURE EVIDENCE:

There were signs of moisture on the left basement wall. The area was dry at the time of the inspection. Dampness on basement walls is not always a sign of water intrusion. The dampness can be the result of warm humid air making contact with cool walls. In many cases the humid air condenses on the wall and forms a layer of moisture. It is important to assess whether moisture on the basement walls is the result of water intrusion or condensation. In this case, the efflorescence noted on the wall appears to be the result of moisture buildup on the exterior side of the foundation. The exterior grading in the affected area is questionable. Many water intrusion problems can be controlled by improving the drainage on the exterior of the home. It is important that all roof drainage and surface water is directed away from the foundation. Any concern about this condition should be referred to a qualified contractor for evaluation and recommendations.



Left



Front

INFORMATIONAL NOTE: BASEMENT STORED ITEMS:

The basement was cluttered with many stored items and/or shelves at the time of inspection, therefore several areas were unable to be inspected.



Please note that it is not within the scope of this inspection to determine or predict the amount or frequency of past or future water intrusion into the basement. HomeTeam will make its best effort in accordance with the ASHI Standards of Practice to determine, based solely on visible conditions at the time of the inspection, whether there is any evidence of ongoing water penetration in the property. You should use all available resources including the seller disclosure and information from the current owner to determine if any water issues exist. Consult with a company specializing in water proofing if you require a guarantee of a 100 percent dry basement.

FLOOR-STRUCTURE

The visible floor structure consisted of a wood planking subfloor, supported by two-inch by ten -inch wood joists spaced sixteen inches on center. There were no material defects observed in the visible portions of the floor structure.

NOTE: EVIDENCE OF TERMITE ACTIVITY:

Evidence of termite activity was noted on the basement floor joists. The visible damage noted was insignificant and did not appear to have any structural significance. Repairs to the affected area (s) did not appear to be necessary. Please note too that any assessment as to the extent of damage caused by termites is limited to the visible and readily accessible areas of the home. We are not able to determine the presence or extent of concealed damage.



Tunnel

NOTE: WATER MARKED FLOOR STRUCTURE:

The floor joists are water marked below the kitchen basement floor structure. The area was dry at the time of the inspection. The wood on the affected area was not rotted. Repairs to the affected area does not appear to be necessary.No immediate action is required.



WATER-METER

The water meter was located in the basement. The main water shutoff valve for the home was located adjacent to the water service entry point in the basement. Water shutoff valves are visually inspected only. No attempt is made to operate the main or any other water supply shutoff valves during the inspection. These valves are infrequently used and could leak after being operated. The only exception to this policy is made when the main water supply valve is off upon arrival at the inspection. Since it is the buyers right to have all utilities operable for the home inspection, we will attempt to turn the main water valve on for the inspection. The HomeTeam is not responsible for leaks caused by operating the valve.



Shut off

PLUMBING

The visible water supply lines throughout the home were copper pipe. The water was supplied by a public water supply. Water valves are not tested as part of the home inspection. Water valves that have not been operated for an extended period of time often leak after being operated. We would not be able to repair a leaking valve during the home inspection. The visible waste lines consisted of cast iron and PVC pipe. The functional drainage of the drain waste lines appeared to be adequate at the time of the inspection. The home was connected to a public sewer system. The under-floor drain lines are considered underground utilities and are specifically excluded from the inspection. The lines are not visible or accessible and their condition cannot be verified during a visual home inspection. Simply running water into plumbing fixtures or floor drains will not verify the condition of the waste line infrastructure under the home. Consult with a qualified plumber for a video camera inspection of the sewer laterals if there is any concern as to the condition of the waste lines under the home. A video scan is the only way to confirm the condition of the drain system. Our inspection of the plumbing system is a functional inspection only. We make no attempt to validate that the plumbing system complies with any codes. Additionally, we cannot validate the workmanship of the plumbing system to be up to standard. We are generalists and do not claim to know everything about any trade. Any concern about the quality or adequacy of the plumbing system should be referred to a qualified, reputable plumber. All plumbing fixtures not permanently attached to a household appliance were operated and inspected for visible leaks. Water flow throughout the home was average. Water pressure was tested at the laundry tub and found to be 60 to 70 pounds per square inch. There were no material

defects observed in the visible portions of the plumbing system.

GAS METER

The gas meter was located in the front yard. The gas supplier for the home based on the identification tag on the meter is Columbia. The main gas valve is usually located at the gas meter and requires a wrench to operate. All visible and readily accessible valves and fittings are tested for leaks using an electronic gas leak detector. No leaks were detected. There was no noticeable odor of gas detected at the time of the inspection. The exterior gas line is below grade, classified as underground utilities and cannot be inspected. HomeTeam recommends enrolling in the gas company's line protection program. The program is available for a low monthly fee, and will cover the majority, if not all of the replacement cost of the main exterior gas line in the event it fails.

INFORMATIONAL NOTE: GAS APPLIANCES THAT ARE OFF:


In the interest of the safety of the inspector and everyone involved, we will not make any attempt to light pilots that are extinguished. It is possible that the gas used to keep a flame lit will continue to flow. If this continues, its concentration may reach a point where a spark or flame will cause a flare up or flashback. We suggest that if it is noted in this report that a gas appliance was not tested because the pilot or gas was off, that you consult with the property owner to have the appliance placed back in to service and tested by a qualified contractor.

WATER HEATER

There was a 50 gallon capacity, natural gas water heater located in the closet. The water heater was manufactured by Bradford White, model number MI5035FBN and serial number LX35091262. Information on the water heater indicated that it was manufactured approximately 12 years ago. A temperature and pressure relief valve (T & P) was present. Because of the lime build-up typical of T & P valves, we do not test them. An overflow leg was present. It did terminate close to the floor. Your safety depends on the presence of a T & P valve and an overflow leg terminating close to the floor. There was an adequate venting system from the water heater to the exterior of the home. The water heater was on and functional. In cases where the water heater is not on at the time of the inspection, it is not possible for us to verify that hot water is present at all plumbing fixtures, nor can we ensure that mixing hot and cold water to achieve a comfortable water temperature works at the fixtures.

ELECTRIC SERVICE

The overhead electric service wire entered the home on the right rear wall. The electric meter was located on the exterior wall. The service entrance cable consisted of stranded aluminum rated for 200 amps. The service wire entered a General Electric service panel, located on the basement wall with a 200 amp and 120/240 volt rated capacity. The main service disconnect switch was located in the main panel. The branch circuits within the panel were copper. These branch circuits and the circuit breaker to which they were attached appeared to be appropriately matched. The internal components of the service panel, i.e. main lugs, bus bars, etc were in good condition. The visible house wiring consisted primarily of the Romex type and appeared to be in good condition. An electric service grounding system was installed. Service grounding requirements have changed many times over the years. The grounding system for a 30-year-old electric service is different from that of a 10-year-old service. The inspection does not attempt to verify that the grounding system or any other part of the electric service complies with current codes.



A representative number of installed lighting fixtures, switches, and receptacles located throughout the home were tested. Please note that it is not always possible for us to identify the purpose of every switch in the home. Switches

may appear to be inoperable or serve no purpose for a variety of reasons, some of which include switches installed for future use, abandoned switches as part of renovation activities or those that operate a device under special conditions such as the heating of gutters in the winter. Specific questions about the purpose of unidentifiable switch uses should be directed to the current property owner. The grounding and polarity of receptacles within six feet of plumbing fixtures, and those attached to ground fault circuit interrupters (GFCI), if present, were also tested. The installation of GFCI protected circuits and/or outlets located within six feet of water, in unfinished basement areas, garage and the exterior of the home is a commonly accepted practice and required by many municipalities. All GFCI receptacles and GFCI circuit breakers should be tested monthly. There were GFCI protected circuits in the home. The present and tested GFCIs were tested and found to be functional.

The electrical service appeared to be adequate. Alarms, electronic keypads, remote control devices, landscape lighting, telephone and television, and all electric company equipment were beyond the scope of this inspection. An electrical inspection sticker placed by an independent firm certified to do electrical inspections was present. Some jurisdictions require an independent electrical inspection and sticker within the last 5 years as a requirement to obtain an occupancy permit. While the requirement to obtain an occupancy permit is usually the sellers, HomeTeam is providing information on the presence of the electrical inspection sticker as a courtesy. There were no material defects observed in the electrical system.

SMOKE-ALARMS

There were smoke alarms found in the house. Property maintenance codes vary from area to area. Some municipalities require smoke alarms in every bedroom, while others only require them on each floor. Check with the local code enforcement officer for the requirements in your area. For safety reasons, the smoke alarms should be tested upon occupancy. The batteries (if any) should be replaced with new ones when you move into the house, and tested on a monthly basis thereafter.

CARBON MONOXIDE DETECTOR

HomeTeam recommends installing carbon monoxide detectors in the home. The detector will alert the occupants of the home to the presence of dangerous carbon monoxide caused by a malfunctioning gas appliance. Multi-function devices exist that provide protection for carbon monoxide, smoke and fire. We are not always able to determine if these types of devices are installed. Many carbon monoxide alarms plug into a standard outlet and can easily be removed by the previous owner. You should verify the types of devices installed in your home, replace the batteries and test immediately after closing.

WINDOWS, DOORS, WALLS AND CEILINGS

A representative number of accessible windows and doors were operated and found to be functional. The primary windows were constructed of aluminum, double hung style, with insulated glass. We test all operable windows with unobstructed access. We do not comment on the presence or condition of window screens or storm windows. Additionally, windows with access blocked by furniture or personal affects, or those covered with plastic or other stationary interior storm windows are not operated. All exterior doors were operated and found to be functional. The exterior door locks should be changed or rekeyed upon occupancy. Possible problem areas may not be identified if the windows or doors have been recently painted. We do not comment on the presence or condition of storm doors, weather stripping or door insulating materials unless their condition represents a safety concern. There were no material defects observed in the windows or doors.


NOTE: DEFECTIVE TILT LATCH:

One or more defective tilt latches were noted on the windows. The tilt latch facilitates easier cleaning by permitting the window to tilt inward when the latches are released. Defective latches permit the window to tilt or fall inward during normal opening. The latches should be replaced.



SAFETY NOTE: WINDOW LOCKS:

3 window (s) would not lock. The window (s) were located in the master bedroom For personal security all windows should properly lock.



INFORMATIONAL NOTE: LIVING AREA CLUTTER:

The interior living area and/or the closets were cluttered with many stored items and/or shelves at the time of inspection, therefore several areas were unable to be inspected.


SKYLIGHTS

There were two skylights installed. Skylights are considered roof penetrations and require water tight installation. Our ability to verify that the skylight is water tight is limited to our visual inspection. In order to ensure the unit remains water tight, we will not attempt to open units that contain this feature. Skylight lens' are made of either plexiglas, lexan or

glass. It is not always possible to identify the lens material. Plexiglas and lexan skylight lens' often develop hairline cracks as the lens material ages. This is usually a cosmetic condition and does not affect the performance of the skylight. In this case hairline cracks were not observed. The skylight lens were clear. Skylights are usually double pane. Depending upon the angle of the sun and the frosting of the glass we cannot always determine if the thermal seal is intact. There were visual defects observed on the skylights.

NOTE: WATER MARKS, FIRST LEVEL:

Water marks with some surface damage was noted on the ceiling at a skylight. The water marks appeared to be the result of active leaks. Consult with a qualified roofer for evaluation and repair.



moisture meter reading



The interior wall and ceiling surfaces were finished with drywall and plaster. The interior wall and ceiling structure consisted of wood framing. Possible problem areas may not be identified if the interior wall and ceiling surfaces have been recently painted. Since the finished wall material and framing are different materials, they expand and contract at different rates. As a result, it is common to see cracks on the finished surface especially around door and window openings and ceilings. These cracks are cosmetic and generally have no structural significance. There were no material defects observed in the interior walls or ceilings.

FIRST LEVEL

The first level consisted of a living / dining room, kitchen and 1/2 bath, an office and a sunroom. The HomeTeam inspects for evidence of structural failure and safety concerns only. The cosmetic condition of the paint, wall covering, carpeting, window coverings, etc., are not addressed. There were no material defects observed on the first level.

The visible portions of the cabinets and counter tops were in fair condition. The appliances were turned on to check operational function only. No consideration is given regarding the age or components that may be worn or otherwise affected by wear and tear or use. No warranty, express or implied, is given for the continued operational integrity of the appliances or their components.

The kitchen contained the following appliances:

The Samsung electric built-in oven was inspected and did appear to be functional. The accuracy of the clock, timers and settings on ovens are not within the scope of this inspection. Please note that many new ranges come with an anti-tilt bracket that is supposed to be attached to the wall and to the back of the range. The purpose of the bracket is to ensure that the range does not tilt forward when the oven door is open and racks are pulled out. We do not verify that the bracket is or is not installed at the inspection. Doing so would require us to pull the range away from the wall, risking scratching or other damage to the finished floor. consult with an appliance service for further evaluation if you want to be sure the bracket is installed.

INFORMATIONAL NOTE: RANGE ANTI TIP BRACKET:

Newer ranges include an anti-tip bracket designed to provide protection when excess force or weight is applied to an open oven door. The bracket is not visible or readily accessible since it is usually installed beneath a rear foot. Applying excessive force on the oven door can damage the hinge or spring so, we do not confirm the presence of a bracket. HomeTeam recommends that anti-tip brackets be installed on all free-standing ranges.

The Samsung electric built in range was inspected and did appear to be functional. The accuracy of the clock, timers and settings on ovens are not within the scope of this inspection. Please note that many new ranges come with an anti-tilt bracket that is supposed to be attached to the wall and to the back of the range. The purpose of the bracket is to ensure that the range does not tilt forward when the oven door is open and racks are pulled out. We do not verify that the bracket is or is not installed at the inspection. Doing so would require us to pull the range away from the wall, risking scratching or other damage to the finished floor. consult with an appliance service for further evaluation if you want to be sure the bracket is installed.

INFORMATIONAL NOTE: RANGE ANTI TIP BRACKET:

Newer ranges include an anti-tip bracket designed to provide protection when excess force or weight is applied to an open oven door. The bracket is not visible or readily accessible since it is usually installed beneath a rear foot. Applying excessive force on the oven door can damage the hinge or spring so, we do not confirm the presence of a bracket. HomeTeam recommends that anti-tip brackets be installed on all free-standing ranges.

The Unbranded range hood was inspected and did appear to be functional. The exhaust capacity is not within the scope of this inspection. Cleaning the fan and filter may increase the exhaust capability.

The Samsung refrigerator was inspected and did appear to be functional. The temperature setting and ice maker, if present, are not within the scope of the inspection.

The Samsung dishwasher was tested and did appear to be functional.

The In-Sink-Erator disposal was inspected and did appear to be functional. The efficiency rating and chopping / grinding ability of the unit is not within the scope of the inspection.

INFORMATIONAL NOTE: CLOTHES DRYER CONNECTIONS:

This note is supplied for informational purposes only, as many clients want to know the type of dryer connections available to them. The absence of either type dryer connection is not a problem. A 240 volt outlet for an electric clothes dryer was installed in the laundry area. If an outlet is present, no attempt was made to verify that the outlet is properly wired or that power is present. A gas connection was not available for a gas clothes dryer. For safety reasons, no attempt was made to verify the presence of gas service at the visible gas dryer connection. Consult with a qualified contractor if the desired type of connection is not available.

A dryer vent was installed. The visible portions of the dryer vent was inspected and did appear to be functional. The venting was adequate to vent the dryer to the exterior of the home.

SECOND LEVEL

The second level of the home consisted of three bedrooms, a master bath and one full bath. There were no material defects observed on the second level.

The second floor stairway was inspected and there were no material defects observed with the steps, stairways or handrails.

THIRD LEVEL

The third level consisted of one bedroom and one full bath. There were no material defects observed on the third level.

The third floor stairway was inspected and there were no material defects observed with the stairs.

SAFETY NOTE: MISSING HANDRAIL:

There is a missing handrail on the stairs leading to the 3rd floor. This can be a safety concern. Local building codes may also require the installation of a handrail.



FIREPLACE

There was one fireplace in the home. The visual condition at the time of the inspection is indicated as follows.

As with all elements of the home inspection, the fireplace inspection is not technically exhaustive. The inspection provides a general condition report only. The fireplace inspection does not include the interior of flues or chimneys, draft characteristics, chimney or firebox integrity or the adequacy of draft, airflow or makeup air. Consult with a qualified, reputable chimney and fireplace professional for a complete evaluation of the fireplace and chimney. Care must be taken to ensure that any flue vent / damper is open during use. All solid fuels such as wood as well as gas logs emit carbon monoxide which is not visible and has no odor. Proper venting ensures that all fire byproducts are vented to the exterior. For safety reasons, a fireplace and the chimney or pipe to which it is vented should be cleaned and re-inspected as there may be hidden defects, not fully visible at the time of the inspection. The fireplace was not tested for operation or function.

An unvented gas fireplace was located in the living room. The unit was visually inspected and did appear to be

functional. Many of these units are controlled by a wall mounted switch. Some operate by remote control, while others are controlled from the base of the unit. These units usually come with an instruction plate that is attached to the unit inside the control access panel. Be sure to read and understand the operating procedures prior to operating the unit. There were no material defects observed on the unvented gas fireplace.



ATTIC STRUCTURE

The attic was accessed through a door in the 3rd level bedroom. The attic above the living space was insulated with batted insulation, approximately 4 -inches in depth. We do not disturb insulation. As a result any issues concealed by insulation will not be identified.

The attic ventilation appeared to be questionable. A thermostatically controlled attic fan was not installed. Attic fans are not tested as part of the home inspection.

The roof structure consisted of two-inch by six -inch wood rafters spaced 16 inches on center and wood planks sheathing. The ceiling structure consisted of two-inch by six-inch rafters spaced 16-inches on center.

Because of the configuration of the framing, which limited access, it was not possible to inspect all areas of the attic. We will not walk on un-floored areas of the attic.

There was no moisture visible in the attic space.

As with all aspects of the home inspection, attic and roof inspections are limited in scope to the visible and readily accessible areas. Many areas of the roof are not visible from the attic especially near the base, where the largest volume of water drains. The presence of or active status of roof leaks cannot be determined unless the conditions which allow leaks to occur are present at the time of the inspection. Please be aware that rain alone is not always a condition that causes a leak to reveal itself. The conditions that cause leaks to occur can often involve wind direction, the length of time it rains, etc. The inspection does not offer or imply an opinion or warranty as to the past, present or future possibility of roof, skylight, flashing or vent leaks. There were no material defects observed in the attic or roof structure.

NOTE: ATTIC VENTILATION:

The attic ventilation was questionable. No vents could be viewed Proper ventilation in the summer helps extend the life of asphalt / fiberglass roofing, as well as reducing radiated heat from the attic to the living space. Proper ventilation in the winter allows heat loss from the living area to exit the home, preventing the possibility of condensation forming in the attic, which could create mold conditions. There was no visual evidence of ventilation related issues in the attic at the time of the inspection. Proper attic ventilation requires creation of natural convection by not just the number of vents installed, but also the location of the vents. It is beyond the scope of the home inspection to determine the adequacy of attic ventilation. Consult with a qualified roofer for further recommendations.


HEATING SYSTEM

The heating system was inspected by HomeTeam. Annual maintenance of the heating and cooling equipment is essential for safe and efficient performance, which will maximize the system's useful life. The results of our visual and operational inspection of the heating system is described below. Periodic preventive maintenance is recommended to keep this unit in good working condition. The home was heated by a Weil Mclain natural gas boiler, Serial Number

CP8042213, Model Number EVG155 which is approximately 4 years old. The unit was located in the basement of the home. It has an approximate net heating capacity of 155,000 BTUH. A carbon monoxide detector with probe was inserted into the main plenum just above the heat exchanger. There NA measurable level of carbon monoxide detected at the time of the inspection. LIMITATION: Examination of heating systems is mechanically limited since the unit cannot be dismantled to examine all of the interior components. Without removing the burners to gain complete access, and with the limited viewing area of the heat exchanger, a thorough inspection is not possible. The inspection does not include a heat-loss analysis, heating design or adequacy evaluation, energy efficiency assessment, installation compliance check, chimney flue inspection, draft test or buried fuel tank inspection. The PVC venting system was adequate to exhaust the spent gases to the exterior of the home and was in good condition.

NOTE: LEAKY CONTROLLER:

There was evidence the boiler control was leaking. Consult with a qualified plumber for repair.



NOTE: INOPERABLE BOILER:

The boiler was not functional at the time of the inspection. The unit was in shut down mode due to high outside temperatures. Consult with a qualified heating contractor to confirm operation if desired.



MINI-SPLIT SYSTEM

The mini-split heating and cooling system was inspected by HomeTeam. Annual maintenance of the heating and cooling equipment is essential for safe and efficient performance, which will maximize the system's useful life. The results of our visual and operational inspection of the heating system is described below. The basement family room was heated and cooled by an Fujitsu electric heater and air conditioner, Serial Number JQNO12622, Model Number AOU9RLS2 . The condensing unit was located on the right hand side of the house of the home. LIMITATION: Examination of heating systems is mechanically limited since the unit cannot be dismantled to examine all of the interior components. The electric heating elements can and will fail. The heating elements fail just like a light bulb; they are working one minute and not the next. These types of systems are usually designed to condition the air in a defined

space of a home. The heating and cooling system was found to be functional. These units generally require very little maintenance, but should still be evaluated regularly to be sure the unit is performing at its top efficiency. Filters, if present should be cleaned or replaced on a regular basis.



A condensate pump was installed on the HVAC system. A condensate pump drains the water produced by the furnace, air conditioner and humidifier overhead to another location in the home. The condensate pump drained to the laundry tub.

ELECTRIC BASEBOARD HEAT

The heating system in the living area consisted of electric baseboard units controlled by either wall-or unit mounted thermostats. The thermostats were turned up during the inspection and appeared to be functional. Electrical heating units require minor servicing and upkeep. The metal fins within the units should be kept clean and the surrounding area should be left open to allow for sufficient airflow.



AIR CONDITIONING

The electric outdoor air conditioner condensing unit was a Comfortmaker, Model Number CSH642GKA101 and Serial Number E223920683. The unit is located on the right side of the home. This unit is approximately 4 years old. Periodic preventive maintenance is recommended to keep this unit in good working condition. The forced air cooling system was tested and found to be functional. The home inspection does not include a heat-gain analysis, cooling design or adequacy evaluation, energy efficiency assessment, installation compliance check or refrigerant evaluation.



NOTE: A/C LINE SET INSULATION:

The insulation on the exterior air conditioning line set is damaged. This could affect the efficiency of the system and should be replaced.



AIR HANDLER:

An air handler was installed in the attic. Air handlers generally contain a blower and heating or cooling elements, and usually connect to a ductwork ventilation system that distributes the conditioned air through the building and returns it to the air handler unit. While there is little maintenance required of an air handler, the unit should be reasonably accessible for service if required. In this case the air handler was reasonably accessible. We do not dismantle air handlers during the home inspection. The condensate drain lines appeared to be in working condition. There were no visual defects noted with the air handler.



Condensation water

NOTE: CONDENSATE:

Water was noted in the attic air handler condensate pan. The condition appears to be the result of high temperatures and humidity in the attic. The system was operating as designed. If desired, the attic space will have to be modified to better control the air temperature. Repairs should be made by a qualified contractor if desired.

There will be normal temperature variations from room to room and level to level, most noticeable between levels.

Airflow throughout the house may be balanced by adjusting any dampers in the supply ducts, or by adjusting the supply registers. Inspection of air and duct supply system for adequacy, efficiency, capacity or uniformity of the conditioned air to the various parts of the structure is beyond the scope of the home inspection.

CONTROLS

The control for the heating and air conditioning system was a 24 volt thermostat located on the living room and office wall of the home. The thermostat was found to be in working order.

PEST INSPECTION

The purpose of the pest inspection is to determine if there are active wood destroying insects present in the home. The pest inspection does not include determining the presence of common household insects such as spiders, ants, etc. The pest inspection was performed by Bill King of Quality Pest Services, a state licensed technician. Their completed report was provided at the time of the inspection.

RADON

Radon, the second leading cause of lung cancer, is a radioactive gas that comes from the natural breakdown of uranium in soil and rock and gets into the air you breathe. It moves through the ground and into your home through cracks and other holes in the foundation where it can accumulate to unsafe levels. Because it is odorless, colorless, and tasteless, testing is the only way to know if you and your family are at risk from radon. There are simple ways to fix a problem if needed. (source; Pa Department of Environmental Protection website) The radon test you requested was performed by HomeTeam, a state certified radon testing firm.. An active radon mitigation system was installed.

NOTE: RADON MITIGATION SYSTEM:

The radon mitigation system installed in the home did not appear to be working properly at the time of the inspection. Consult with the original installer whose name is usually located on a label affixed to the system in the basement for evaluation and repair.



REASONABLE EXPECTATIONS REGARDING A PROFESSIONAL HOME INSPECTION:

There may come a time when you discover something wrong with the house, and you may be upset or disappointed with your home inspection. There are some things we'd like you to keep in mind.

Intermittent or concealed problems: Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the tap. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets are lifted, furniture is moved or finishes are removed.

No clues: These problems may have existed at the time of the inspection, but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is unfair to assume we should foresee a future problem.

We always miss some minor things: Some say we are inconsistent because our reports identify some minor problems but not others. The minor problems that are identified were discovered while looking for more significant problems. We note them simply as a courtesy. The intent of the inspection is not to find the \$200 problems; it is to find the \$1000 problems. These are the things that affect people's decisions to purchase.

Contractor's advice: A common source of dissatisfaction with home inspectors comes from comments made by contractors. Contractors' opinions often differ from ours. Don't be surprised when three roofers all say the roof needs replacement, when we said that the roof would last a few more years with some minor repairs.

"Last man in" theory: While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the "last man in" theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether or not the roof leak is his fault. Consequently, he won't want to do a minor repair with high liability, when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

Most recent advice is best: There is more to the "last man in" theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we unfortunately find ourselves in the position of "first man in" and consequently it is our advice that is often disbelieved.

Why didn't we see it?: Contractors may say, "I can't believe you had this house inspected, and they didn't find this problem." There are several reasons for these apparent oversights:

- **Conditions during inspection:** It is difficult for homeowners to remember the circumstances in the house at the time of the inspection. Homeowners seldom remember that it was snowing, there was storage everywhere or that the furnace could not be turned on because the air conditioning was operating, etc. It's impossible for contractors to know what the circumstances were when the inspection was performed.
- **This wisdom of hindsight:** When the problem manifests itself, it is very easy to have 20/20 hindsight. Anybody can say that the basement is wet when there is 2" of water on the floor. Predicting the problem is a different story.
- **A long look;** If we spent half an hour under the kitchen sink or 45 minutes disassembling the furnace, we'd find more problems, too. Unfortunately, the inspection would take several days and would cost considerably more.
- **We're generalists:** We are generalists; we are not specialists. The heating contractor may indeed have more heating expertise than we do. This is because we are expected to have heating expertise and plumbing expertise, structural expertise, electrical expertise, etc.
- **An invasive look:** Problems often become apparent when carpets or plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We don't perform invasive or destructive tests.

Not insurance: In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy. The premium that an insurance company would have to charge for a policy with no deductible, no limit and an indefinite policy period would be considerably more than the fee we charge. It would also not include the value added by the inspection.

Reprinted from ASHI Reporter, By Permission of Alan Carson, Carson Dunlop & Assoc.