



Re: 850 Ammons Rd - Filter Quote

From john jacobs <eastestinglab@gmail.com>

Date Mon 2/9/2026 10:50 AM

To Kayla Stewart <KS@vignetterealty.com>

Kayla,

We examined the present system at 850 Ammons Road. For some reason the system was unplugged and set on bypass.

We turned the system back on and found the following.

1. Reduced flow probably from clogged tanks.
2. The iron level before the system was 0.646 ppm after 0,385. Both levels are above the maximum allowed limit set by the EPA and State of NC.
3. The system is older.
4. We recommend a new system.

Thanks

EAS Testing Lab

John Jacobs

On Mon, Feb 9, 2026 at 9:27 AM Kayla Stewart <KS@vignetterealty.com> wrote:

Can I please get a quote in writing for the filter at 850 Ammons Rd, and an explanation of what will be replaced?



Kayla Stewart

📞 8282206387

✉ kayla@vignetterealty.com

VIGNETTE REALTY

53 E Main St, Ste J, Franklin, NC 28734

