



Clean, Preserve...Protect Environmental Specialists

June 11, 2025

Mr. Jonathan Maurer
15 Burritts Landing North
Westport, CT 06880

Subject: Tank Removal, June 6, 2025
Mauer Residence
15 Burritts Landing North
Westport, Connecticut

Dear Mr. Maurer:

On June 6, 2025, Enviroshield personnel completed the removal of one underground 550-gallon fuel oil tank located at the subject property. The former location of the tank and progression of the tank removal process is shown in Site Photographs enclosed with this letter.

Prior to the removal of the tank, all liquid, sludge sediment and rinse water were pumped and cleaned from the tank for disposal by Enviroshield, Inc., a State of Connecticut licensed waste transporter at Safety-Kleen Systems, Inc., 120 Forbes Avenue, New Haven, Connecticut.

The top of the tank was exposed and enough soil was removed from the excavation to pull the tank from the ground. The tank was thoroughly inspected for rust, cracks, holes, or other physical characteristics, which could have been cause for a fuel release. No evidence of a fuel release was observed.

Soil samples obtained from the tank grave were field screened using a Photo Ionization Detector (PID); the results of the field screening indicated no evidence of a fuel release.

A soil sample was obtained from underneath the former tank and submitted to Complete Environmental Testing (CET) for analysis by Connecticut Extractable Total Petroleum Hydrocarbons (ETPH). This analysis is an industry standard for detecting #2 heating oil in soil.

As indicated in the attached CET laboratory report #25F0188, the reported result for the sample tested is below the laboratory detection limit for ETPH; no petroleum was detected within the sample.

Page 2 of 2
June 11, 2025
Maurer Residence
15 Burritts Landing North
Westport, Connecticut

The tank was transported, cleaned, and disposed of at P.C. Metals, Inc., 270 Central Avenue, Bridgeport, Connecticut in a manner consistent with industry standards and in compliance with all Local, State and Federal Codes and Regulations.


The tank grave was backfilled to grade.

Based on visual observations, PID field screening and laboratory analysis, Enviroshield found no indication of the tank system's failure.

If you have any questions concerning any of this work, please contact me at your earliest convenience at (203) 380-5644.

Sincerely,

Enviroshield, Inc.



Leonard Bochicchio
Senior Project Manager

Enclosures

cc: Attorney W. Glenn Major via email wgmajor@pullcom.com
Westport Building Department via email monofrio@westportct.gov
Permit #TANK-2025-01064

