

May 30, 2024

MAYFAIR HOUSE ASSOCIATION, INC.

c/o Castle Group 12270 SW 3rd Street, Suite 200 Plantation, FL 33325

Phone: 203-588-6305

Email: tcallahan@castlegroup.com

Subject: Summary of Report of Engineering Consulting Services

MILESTONE INSPECTION - PHASE I SUMMARY

Mayfair House Condominium 3589 South Ocean Boulevard

Palm Beach, Palm Beach County, Florida 33480

SOCOTEC Project Number D437-001.01

SOCOTEC Consulting, Inc. (SOCOTEC) is pleased to present this Milestone Inspection - Phase I summary letter completed for the subject building. The Mayfair House Condominium has a 9-story mid-rise structure that is located along South Ocean Boulevard in South Palm Beach, Palm Beach County, Florida. The building contains 91-individual residential units plus 42 lanai units and was developed circa 1974.

Material Findings

Following the completion of our phase I milestone inspection for the subject property, we **did not** observe conditions that we considered **substantial structural deterioration**, or pose a threat to the public health, safety, or welfare of the subject property. We reserve the right to amend our opinion should new information be brought to our attention.

Remedial/Preventive Repair Recommendations

During our phase I inspection we observed the following building components that should be considered for repair/replacement within the near future. Please note that these items are not considered substantial structural deterioration:

- Opened walls from water intrusion in Units 601, 609, 814, & 805.
- Deterioration to interior spaces from water intrusion in Units 501, 701, 714, 812, & PH12.
- Cracks in seawall piers.

Crinkled metal deck in stairwells.

We appreciate working with you as your engineering consultant. We recommend that you read this report thoroughly and contact us with any questions.

Sincerely,

SOCOTEC CONSULTING, INC.



Eric Culver

Connor Malnack Project Engineer Eric Culver, P.E. Senior Engineer Florida Registration No. 89911

Note: Please review our full Milestone Inspection Phase I Report which includes the details of our inspection and the known specifics regarding the design and construction of the subject building.

Distribution: 1 – Addressee (via email), 1 – File