

238 Grant Avenue, Ross Township, PA 15237

Seller completed the following works after the home inspection:

Installed GFCI Outlet

Repaired bathroom light switch

Drain capped under kitchen sink

Gutters cleaned to prevent leaking

Soffit re-secured

Slow draining sink cleared/cleaned

Electrical service cable secured

Some tree branches trimmed

DocuSigned by:
 6/22/2026 | 7:08 AM PDT
E071D9F161DF46E...