

STATE OF TEXAS WELL REPORT for Tracking #543094

Owner: **Craig Hunt** Owner Well #: **No Data**
Address: **126 Ridge Wood
Fredericksburg, TX 78624** Grid #: **57-42-1**
Well Location: **279 Achtzehn
Fredericksburg, TX 78624** Latitude: **30° 20' 29.72" N**
Longitude: **098° 51' 46.27" W**
Well County: **Gillespie** Elevation: **No Data**

****This well has been plugged****

Plugging Report Tracking #199843

Type of Work: **New Well** Proposed Use: **Domestic**

Drilling Start Date: **4/24/2020** Drilling End Date: **4/24/2020**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	8	0	167

Drilling Method: **Air Rotary**

Borehole Completion: **Filter Packed**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Filter Material</i>	<i>Size</i>
Filter Pack Intervals:	50	167	Gravel	3/8

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	-2	50	Cement 8 Bags/Sacks

Seal Method: **Pressure**

Distance to Property Line (ft.): **50+**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Sleeve Installed** **Surface Completion by Driller**

Water Level: **55 ft. below land surface on 2020-04-24** Measurement Method: **Steel Tape**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Estimated** **Yield: 10-12 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
71 - 72	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Magill Drilling & Water Well Service, LLC**
PO Box 46
Castell, TX 76831

Driller Name: **Zane Magill**

License Number: **4168**

Comments: **No Data**

Report Amended on 5/14/2020 by Request #31784

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	1	Topsoil
1	12	White Limestone
12	68	Red Sandy Clay
68	165	Red Limestone
165	167	Red Granite

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4.5	Blank	New Plastic (PVC)	40	-2	147
4.5	Screen	New Plastic (PVC)	40 0.020	147	167

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540