

Get Track No 356984

STATE OF TEXAS WELL REPORT for Tracking #356984

Owner: **HAFH-RM,LLC.** Owner Well #: **3**
 Address: **1301 W 25th St. Suite #510** Grid #: **57-37-3**
Austin, TX 78705
 Well Location: **4713 FM 962 (Lot 4)** Latitude: **30° 27' 41" N**
Round Mountain, TX 78636 Longitude: **098° 24' 43" W**
 Well County: **Blanco** Elevation: **No Data**

Type of Work: **New Well** Proposed Use: **Domestic**

Drilling Start Date: **2/24/2014** Drilling End Date: **2/25/2014**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	8	0	15
	6.25	15	820

Drilling Method: **Air Hammer**
Borehole Completion: **Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	0	50	7port

Seal Method: **Slurry** Distance to Property Line (ft.): **50+**
 Sealed By: **Driller** Distance to Septic Field or other concentrated contamination (ft.): **100+**
 Distance to Septic Tank (ft.): **No Data**
 Method of Verification: **Land Owner**

Surface Completion: **Surface Sleeve Installed**

Water Level: **No Data**
 Packers: **Burlap/Neoprene 470,460,60,50**
 Type of Pump: **No Data**
 Well Tests: **Jetted** Yield: **40 GPM**

	Strata Depth (ft.)	Water Type
Water Quality:	720-820	Hickory

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.