

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
 ☒ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
 Quantity: ☐ Yes ☒ No ☐ Unknown
 Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☒ Yes ☐ No
 If Yes, Date of most recent test: 2020 Are test results available? .. ☐ Yes ☒ No
 To your knowledge, have any test results ever been reported as unsatisfactory
 or satisfactory with notation? ☒ Yes ☐ No
 If Yes, are test results available? ☐ Yes ☒ No
 What steps were taken to remedy the problem? Water softener installed

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Front yard
 Installed by: Wells Unlimited
 Date of Installation: 2003+/-

USE: Number of persons currently using system: 3
 Does system supply water for more than one household? ☒ Yes ☐ No ☐ Unknown

Comments: N/A

Source of Section I information: Seller

Buyer Initials _____ Page 1 of 8 Seller Initials _____

PROPERTY LOCATED AT: 24 Caroline Crossing, Hollis, ME 04042

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... ☐ Yes ☐ No

If Yes, what results: _____

Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No

What steps were taken to remedy the problem? _____

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: **Backyard under patio** OR ☐ Unknown

Date installed: 2003+/- Date last pumped: 11/2023 Name of pumping company: Faulkner Septic Services

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem: N/A

Date of last servicing of tank: N/A Name of company servicing tank: N/A

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: **Backyard**

Date of installation of leach field: 2003+/- Installed by: **Pleasant Hill Excavation**

Date of last servicing of leach field: N/A Company servicing leach field: N/A

Have you experienced any malfunctions? ☐ Yes ☒ No

If Yes, give the date and describe the problem and what steps were taken to remedy: N/A

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☐ Yes ☒ No ☐ Unknown

Comments: Patio stones are removed above tank to provide access. Septic cleanout in basement is covered by drywall. No current access to cleanout. 3-bedroom septic.

Source of Section II information: **Seller/Public Records/Previous Disclosure**

Buyer Initials _____

Page 2 of 8

Seller Initials _____

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	FHW	Electric Radiant		
Age of system(s) or source(s)	2003	2003		
TYPE(S) of Fuel	Oil	Electric		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	~600 gallons delivered in 2024	Unknown, part of elect utility		
Name of company that services system(s) or source(s)	Fielding's	N/A		
Date of most recent service call	12/1/2023	N/A		
Malfunctions per system(s) or source(s) within past 2 years	N/A	N/A		
Other pertinent information	Service scheduled	2nd floor bathroom. Unknown if functional.		

Are there fuel supply lines? ☒ Yes ☐ No ☐ UnknownAre any buried? ☐ Yes ☒ No ☐ UnknownAre all sleeved? ☒ Yes ☐ No ☐ UnknownChimney(s): ☒ Yes ☐ NoIf Yes, are they lined: ☒ Yes ☐ No ☐ UnknownIs more than one heat source vented through one flue? ☐ Yes ☒ No ☐ UnknownHad a chimney fire: ☐ Yes ☐ No ☐ UnknownHas chimney(s) been inspected? ☒ Yes ☐ No ☐ UnknownIf Yes, date: 2010Date chimney(s) last cleaned: unknownDirect/Power Vent(s): ☐ Yes ☒ No ☐ UnknownHas vent(s) been inspected? ☐ Yes ☐ No ☐ Unknown

If Yes, date: _____

Comments: Previous records note that it "needs hy-vents, expansion tank", but seller has not experienced any issues.Source of Section III information: Seller/Previous Disclosure**SECTION IV - HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☐ No ☒ UnknownIf Yes, are tanks in current use? ☐ Yes ☐ No ☒ Unknown

If no longer in use, how long have they been out of service? _____

If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☒ UnknownAre tanks registered with DEP? ☐ Yes ☐ No ☒ Unknown

Age of tank(s): _____ Size of tank(s): _____

Location: _____

Buyer Initials _____

Page 3 of 8

Seller Initials _____

PROPERTY LOCATED AT: 24 Caroline Crossing, Hollis, ME 04042

What materials are, or were, stored in the tank(s)? _____

Have you experienced any problems such as leakage: ☐ Yes ☐ No ☐ Unknown

Comments: None known

Source of information: Seller/Previous Disclosure

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: ☐ Yes ☐ No ☒ Unknown

Comments: None known

Source of information: Seller/Previous Disclosure

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☒ Yes ☐ No ☐ Unknown

If Yes: Date: 2016 By: Nelson Analytical Lab

Results: 16 pCi/L

If applicable, what remedial steps were taken? Radon mitigation system installed by previous owner

Has the property been tested since remedial steps? ☐ Yes ☐ No ☒ Unknown

Are test results available? ☐ Yes ☒ No

Results/Comments: Radon mitigation system installed by previous owner

Source of information: Previous Disclosure

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☐ No ☒ Unknown

If Yes: Date: _____ By: _____

Results: _____

If applicable, what remedial steps were taken? _____

Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown

Are test results available? ☐ Yes ☐ No

Results/Comments: N/A

Source of information: Seller

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☐ No ☒ Unknown

Comments: None known

Source of information: Seller/Previous Disclosure

Buyer Initials _____

Page 4 of 8

Seller Initials _____

PROPERTY LOCATED AT: 24 Caroline Crossing, Hollis, ME 04042

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes ☐ No ☒ Unknown ☐ Unknown (but possible due to age)

If Yes, describe location and basis for determination: _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☐ No

Comments: Home built in 2003. Interior recently repainted. Home has vinyl siding and composite decking on farmer's porch.

Source of information: Seller/Previous Disclosure/Visual Inspection

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☐ No ☒ Unknown

LAND FILL: ☐ Yes ☐ No ☒ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☐ No ☒ Unknown

Other: N/A

Source of information: Seller/Previous Disclosure

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: HOA for road maintenance and insurance/maint for common areas. \$100/quarter in 2025. Returning to \$150/quarter in 2026

Source of information: Seller

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? HOA

Road Association Name (if known): Caroline Crossing Association

Source of information: Seller

Buyer Initials _____

Page 5 of 8

Seller Initials _____

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: _____

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: _____

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?

N/A

Relevant Panel Number: 23031C0143G Year: 2024 (Attach a copy)

Comments: Area of Minimal Flood Hazard - Zone X

Source of Section VI information: FEMA Flood Maps

Buyer Initials _____

Page 6 of 8

Seller Initials _____

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
 ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance including those that are imposed by the state or municipality? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **Propane tank (Maine Gas) for range**

Year Principal Structure Built: **2003** What year did Seller acquire property? **2020**

Roof: Year Shingles/Other Installed: **2003**

Water, moisture or leakage: **None**

Comments: **N/A**

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ☒ Yes ☐ No ☐ Unknown

Comments: **Previous disclosure notes outside spigot froze allowing water into basement. No water intrusion during current ownership.**

Mold: Has the property ever been tested for mold? ☒ Yes ☐ No ☐ Unknown

If Yes, are test results available? ☐ Yes ☒ No

Comments: **Previous disclosure notes property has been tested for mold. No further information provided.**

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: **100 amp service. Generator hookup.**

Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ☒ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
 ☐ Yes ☒ No ☐ Unknown

Comments: **N/A**

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **Wood floor showing wear in some areas. Louvered dryer vent**

Continued... See Addendum Known material defects 1

Comments: **Subdivision plan available, not property-specific boundary survey.**

Source of Section VII information: **Seller/Public Records/Previous Disclosure**

Buyer Initials _____ Page 7 of 8 Seller Initials _____

SECTION VIII - ADDITIONAL INFORMATION

21.4 acres of common space at end of Caroline Crossing extending behind each lot.
Owners have split duties mowing along entrance area.
RR3 Zone calls for 20' side setbacks for clustered subdivisions. Subdivision plan notes Lot 2 through 6(24 Caroline Crossing is Lot 2) are clustered lots. Home appears to be about 50' from right side property line. Buyer to do own due diligence on possibility of construction of garage or outbuilding.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER	DATE	SELLER	DATE
Evan Jewell		Sydney Jewell	
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE

ADDENDUM

PROPERTY: **24 Caroline Crossing, Hollis, ME 04042**

1) Known material defects

cap missing one louver. A small portion of the formica laminate on the island has a chip taken out. Vent (of unknown origin, but possible plumbing vent) appears to vent into attic according to inspection report from 2020. Uneven risers on rear steps. Unknown if light post at end of driveway works. Patio slider has no screen, and needs new exterior handle. Side entry storm door needs adjustment to close and latch properly, and has a damaged screen. No doors on some cabinets. Some wear and tear seen from kids and pets on some interior doors.

Date: _____

Date: _____

Signature _____

Signature _____

Date: _____

Date: _____

Signature _____

Signature _____

Addendum