

By Road

### STATE OF TEXAS WELL REPORT for Tracking #424817

Owner:	<b>David Sawtelle</b>	Owner Well #:	<b>No Data</b>
Address:	<b>110 N. Milam PMB 158 Fredericksburg, TX 78624</b>	Grid #:	<b>57-41-9</b>
Well Location:	<b>.1 Mi. N. of Catholic Cemetery on Metzger Rd; 75' E in field; Well #2 Fredericksburg, TX</b>	Latitude:	<b>30° 17' 27" N</b>
		Longitude:	<b>098° 53' 01" W</b>
Well County:	<b>Gillespie</b>	Elevation:	<b>No Data</b>

Type of Work:	<b>New Well</b>	Proposed Use:	<b>Domestic</b>
---------------	-----------------	---------------	-----------------

Drilling Start Date: **6/17/2016**      Drilling End Date: **6/17/2016**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	<b>9</b>	<b>0</b>	<b>50</b>
	<b>6</b>	<b>50</b>	<b>140</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Filter Packed**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Filter Material</i>	<i>Size</i>
Filter Pack Intervals:	<b>22</b>	<b>50</b>	<b>Gravel</b>	<b>3/8 "</b>

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks &amp; material)</i>
Annular Seal Data:	<b>1</b>	<b>3</b>	<b>Cement 1 Bags/Sacks</b>
	<b>3</b>	<b>22</b>	<b>Bentonite 4 Bags/Sacks</b>

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other  
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Pitless Adapter Used**

Water Level: **30 ft. below land surface on 2016-06-17**

Packers: **No Data**

Type of Pump: **Submersible**      Pump Depth (ft.): **40**

Well Tests: **Jetted**      Yield: **20 GPM**

R-04735

Water Quality: Strata Depth (ft.) 30 - 35 Water Type Good (470 ppmTDS)  
 Chemical Analysis Made: No  
 Did the driller knowingly penetrate any strata which contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: Virdell Drilling Inc.  
 111 E. Grayson St.  
 Llano, TX 78643

Driller Name: James Caleb Virdell

License Number: 59342

Comments: Hole Backfilled 50' - 140'

Report Amended on 6/23/2016 by Request #18091

Lithology:			Casing: BLANK PIPE & WELL SCREEN DATA						
DESCRIPTION & COLOR OF FORMATION MATERIAL			Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)	
Top (ft.)	Bottom (ft.)	Description							
0	1	Topsoil	5		New Plastic (PVC)	SDR17	-2	30	
1	5	Brown Sandy Clay	5		Perforated New Plastic or Slotted (PVC)	SDR17	30	50	
5	17	Red Clay							
17	35	Sand							
35	110	Red Clay & Limestone							
110	132	Brown & Gray Cambrian Limestone							
132	140	Granite Gravel & Clay							

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**  
 TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation  
 P.O. Box 12157  
 Austin, TX 78711  
 (512) 463-7880

R-0473